



TOUCH VOLTMETER RED LEAD HERE WHEN SETTING Vref AXIS VOLTAGE. TYP FOR EACH AXIS

TOUCH VOLTMETER BLACK LEAD HERE FOR ALL MEASUREMENTS

TOUCH VOLTMETER RED LEAD HERE TO CHECK FOR +5VDC BEFORE INSTALLING THE DRIVER CHIPS

HOBBY CNC

©All Rights Reserved