



American Legend Aircraft Company
1810 Piper Lane
Sulphur Springs, Texas 75482
903-885-7000
<http://legend.aero>

SERVICE BULLETIN

American Legend Aircraft Company considers compliance mandatory

Notification Number	SB-07-07-16-1
Subject	Throttle, Front to Rear Connect Cable
Supersedes Notices	None
Release Date	July 16, 2007
Effective Date	July 16, 2007
Required Corrective Action	Replacement
Affected Make	American Legend Aircraft
Affected Models	AL3, AL11
Affected Serial Numbers	AL-1005 through AL-1087

Service to be performed by: The holder of a mechanic certificate with airframe or powerplant rating(s), or both, or a LSA Repairman.

Tools required: 3/8, 7/16 wrench, Phillip and flat screw driver, wire cutters, pliers

Background: The wire cable that connects the rear to front throttle has broken on a small number of aircraft. Additionally the wire was bending or deforming and made the rear throttle hard if not impossible to operate. This never affected the front throttle to engine connection but could bind and cause difficulty in operating the front throttle. American Legend developed a solid stainless steel rod to replace the cable connection. The replacement kit is part number 200-CN0107, Throttle Interconnect Upgrade Service Bulletin:

American Legend Aircraft Company suggest the replacement of the connection cable between the front and rear throttle quadrants for aircraft that are used for instruction are that are soloed from the rear seat. These parts should be replaced during the next annual inspection.

A kit containing this material can be ordered from American Legend Aircraft Company. Kit part number is 200-CN 0107, Throttle Interconnect Upgrade.

It will be the responsibility of the owner/operator to comply with all released SAFETY ALERTS, SERVICE BULLETINS, NOTIFICATION and Airworthiness Directives as applicable. All inspection procedures and maintenance schedules must be accomplished per the manufacturer's recommendations.

For more information please contact us at the above address or by E-mail at

Service@legend.aero