

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
6/23/16	0	5/2	B3D36C429 160328	THIS PROPELLER WAS MANUFACTURED NEW AT McCauley Propeller Systems. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE.	IC 6050



SIGNATURE  
**TECHNICAIR**  
 Aircraft Maintenance  
 A BBA Aviation company

07/08/2016 N#:N6345V MODEL:172RG SN:172RG0636 TT/Tach:6733.6 WO#:S19-16-03421

Installed New McCauley Propeller model B3D36C429/82NPA-6 s/n-160328 in accordance with STC SA495CH per McCauley technical report No. 844 and McCauley Drawing No. D-60165. Operating limits Placard A-60163 was installed per Drawing No. D60165. Engine Tachometer was remarked per TR 844. Run up, leak and ops check was good. Revised Aircraft flight manual with Flight manual supplement TR 843 Weight and balance and equipment list was revised. A FAA form 337 dated 7-8-2016 was submitted.

I certify that the aircraft, aircraft engine, propeller, or appliance identified above was repaired and or inspected in accordance with current FAA regulations and was found airworthy with respect to the work performed and is approved for return to service.

APPROVED BY


Signature TechnicAir Winston Salem NC FAA Repair Station PAIR208A



Service History

Number

Heart of Virginia Aviation  
11152 Airpark Rd  
Ashland, VA 23005



Phone: 804-798-6500  
Fax: 804-798-6544  
03/08/2019

Tach: 6774 N6345V  
ETT: 5779.2 ETSO: 1005.2 ATT: 6774 PTT: 40.4

I certify this Prop has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Daniel Mcsherry AP3110300IA

A handwritten signature in black ink, appearing to read 'Daniel Mcsherry', written over a horizontal line.