



ACF-50

ANTI-CORROSION FORMULA

For industrial use, fleet vehicles, marine, RV, ATV, UTV & snowmobiles



METAL SURFACES

1. Remove accumulation of dirt & grease.
2. Spray or wipe **ACF-50** onto surface with a uniform coating.
3. Apply heavier coat to areas where corrosion is present.
4. Reapply **ACF-50** after any solvent cleaning, contact with chemicals/ acids or when metal surface has been severely damaged by abrasions.

**Product dilutions are determined by extent, condition & soil type.*

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.

QUESTIONS? NUVITE technicians have the answers 800.394.8351