

CG5 OS BUILD REVISION HISTORY

REV 4.1:

- Correction for Drift Start Time as of 2010.
Work around for versions 4.0 and lower:
 - Set RTC Date temporarily to 2009 /12/30
 - In the AutoGrav Setup page capture Drift Start Time (Consult the manual for Info on this)
 - Set RTC Date back to normal local time / date
 - Proceed normally with survey
 - Do not change Drift Start Time for the duration of survey (This is normal procedure)
 - After Cold Boot or Memory Erase ... Please repeat above procedure.
- Correction of display garbling should one unnecessarily change the Baud Rate when using USB KEY dump method

REV 4.0:

- USB memory key support .
- **Cosmetic BUG “ THIS IS NOT A DESTUCTIVE BUG.” ...**
- **Manifestation:**
- ... after data dump via USB key . (Auto Baud Rate select)
- **Symptoms:**
- Manipulation of Baud Rate field (Dump screen) scroll to the right will display improper message selection .
- **Fix:** Scroll to the left few times until proper messages like 9600 baud appears . Leave and reenter the DUMP screen to erase garbled messages . **No need for COLD BOOT .**
- **REV 4.1 corrects this issue.**