

			Kyocera	
Model #	Serial #	Total Count	Notes	Sale Price
P2235dw	VCU9608456	875	Replaced small cracked panel. Added New Full toner. Test OK	\$ 149.00
M3645idn*	R4S9810619	257	Repl broken scan glass. Install new toner. Calibrate, Test OK	\$ 929.00
P3145dn*	R4H0412017	16963	Repl fuser unit, (Warranty). Tested OK.	\$ 279.00
P3145dn*	R4H0412022	6736	Repaired Manual tray lift spring. Tested OK.	\$ 299.00
M3655idn*	R4P0X64279	86	Replaced covers and OP Panel. Test OK	\$ 1,059.00
P3155dn*	R4A0Y20641	2	No problem found. Tested all functions. Test OK - Reset Memory	\$ 539.00
P2235dw*	VCU0Z12042	6	repaired drum unit cover, ran setup to test only. Test ok	\$ 169.00
P2235dw*	VCU1112309	14	replaced DRUM cart and DV (under warranty) & Toner. Setup. Test OK	\$ 169.00
M3645idn	R4S0X16771	4945	Replaced bkn glass, cleaned and calibrated, New Toner, test OK	\$ 859.00
P2235dw	VCU1112283	77	No problem found. Tested all functions. Test OK - Reset Memory	\$ 169.00
M2540dw*	VCI1539384	17	Repl DV unit, cleaned and tested OK (no warranty on DV unit)	\$ 459.00
P3145DN	R4H1522838	0	Cleaned and tested OK. Re boxed in Non OEM box.	\$ 419.00
			KONICA MINOLTA	
4422*	AAFM011000946	77	Improper setup by customer. completed setup w/ date & time. test ok.	\$ 679.00
4700i	ACTA011000223	0	Update firmware, repl bkn cassette, Not return in orig box. Reboxed. Not setup.	\$ 470.00