



ENGINE AFTERMARKET Product Alert

Please forward this to individuals responsible for the Donaldson Parts Program

July 29, 2020

Spin-On Lube Filters

Part Numbers: P552100

P550596


P550777

P551670



Date Codes Affected: Parts produced in Poland on or before February 24, 2020

All lube filters listed above produced in **Poland on or before February 24, 2020** should be removed from your inventory, your customer's inventory and not installed for service. We recommend filters already in use should be removed from engine at the earliest convenience. It has come to our attention that these filters have gaskets that may leak and/or allow the filter to loosen once installed.



Date Code

MON/DD/YY

Made in Poland

