



THE NEXT GENERATION DRYWASH

NPC/3



No Water ▶ Minimal Dust ▶ Low Odor

Designed for exterior paint rejuvenation, NPC/3 offers the same outstanding qualities of the original NUPOWER II DryWash with added benefits...

3-IN-1 FUNCTION WITH MINIMAL DUST & LOW ODOR

✓ **CLEANS/DEOXIDIZES**

Removes soils, fuel residue, carbon, dirt, etc., from surface pits & disintegrates oxidation buildup.

✓ **PRESERVES**

High technology formulation increases gloss & *clean appearance*.

✓ **PROTECTS**

Deposits chemical barrier coating against surface oxidation & UV deterioration

NPC/3 conforms to airframe OEM standards & specs. Its easy *Wipe-On, Wipe-Off* application can be done with pad applicators or by hand. Minimal dust & low odor allow personnel to continue working in conjunction with the DryWash process.



For Normal or Lightly Oxidized Soiled Surface Conditions:

1. Apply NPC/3 "AS IS" by hand, with mop head or random orbital.
2. Agitate an area evenly with the product.
3. Allow to dry 5-10 minutes. It will "haze" over.
4. Remove by buffing-out with clean mop head, or dry terry towel, or a clean bonnet head on random orbital.

For heavily soiled surface conditions: For grease, oil, hydraulic oil buildup, we recommend wiping down or wet washing the area with NUVITE's CITRICUT or SS9-3 degreasers prior to the use of NPC/3, then proceed with above steps.

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.