

C.O.C.: G79656

REPORT No. B20-23119

Report To:

Golden Lake POA
 437 Island View Dr.,
 North Algoma ON K0J 1X0 Canada

Attention: Natalie Corbin

Caduceon Environmental Laboratories

2378 Holly Lane
 Ottawa Ontario K1V 7P1
 Tel: 613-526-0123
 Fax: 613-526-1244

DATE RECEIVED: 07-Aug-20

JOB/PROJECT NO.:

DATE REPORTED: 14-Aug-20

P.O. NUMBER:

SAMPLE MATRIX: Surface Water

WATERWORKS NO.

Parameter	Total Kjeldahl Nitrogen	Phosphorus-Total	E coli		
Units	mg/L	mg/L	cfu/100mL		
R.L.	0.1	0.002	1		
Reference Method	E3199A.1	E3199A.1	MOE E3371		
Date Analyzed/Site	13-Aug-20/K	13-Aug-20/K	07-Aug-20/O		

Client I.D.	Sample I.D.	Date Collected				
Tuckers Island	B20-23119-1	06-Aug-20	0.3	0.009	1	
Cormorant Island	B20-23119-2	06-Aug-20	0.3	0.010	6	
Deepest Part of Lake	B20-23119-3	06-Aug-20	0.3	0.011	0	
Brennans Creek	B20-23119-4	06-Aug-20	0.7	0.033	24	
Trapperman Shoal	B20-23119-5	06-Aug-20	0.3	0.011	0	
Mundts Bay	B20-23119-6	06-Aug-20	0.3	0.008	0	

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie



Greg Clarkin, BSc., C. Chem
 Lab Manager - Ottawa District

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.