



Radon Inspection Report

Measurement of Radon Concentration in Indoor Air

Report nr: 2700006095201811060718
Serial nr: 2700006095

Report generated date: 11/6/18 7:18 PM

Measurement Address:

10690 McCool Drive East
Burnsville, Minnesota 55337
United Statee

Ventilation:

Building type:

Room	Floor	Measurement Start	Measurement End	Measured Value
		11/4/18 4:03 PM	11/6/18 4:03 PM	5.4 pCi/L

Location

November 6, 2018
Date

Signature



Detailed Measurement Data

Units	Min	Max	Average
Radon [pCi/L]	1.5	10.5	5.4
Temperature [°F]	59.4	63.0	61.1
Humidity [%rH]	51	61	59
Pressure [kPa]	97.35	98.11	97.74

Radon measurements for hour 1 to hour 48

Timestamp	Radon [pCi/L]	Timestamp	Radon [pCi/L]	Timestamp	Radon [pCi/L]
Hr. 1 - 11.04 17:03	1.5	Hr. 17 - 11.05 09:03	7.3	Hr. 33 - 11.06 01:03	4.9
Hr. 2 - 11.04 18:03	8.0	Hr. 18 - 11.05 10:03	5.6	Hr. 34 - 11.06 02:03	10.5
Hr. 3 - 11.04 19:03	2.2	Hr. 19 - 11.05 11:03	5.3	Hr. 35 - 11.06 03:03	4.8
Hr. 4 - 11.04 20:03	5.3	Hr. 20 - 11.05 12:03	6.5	Hr. 36 - 11.06 04:03	6.6
Hr. 5 - 11.04 21:03	4.9	Hr. 21 - 11.05 13:03	6.1	Hr. 37 - 11.06 05:03	4.0
Hr. 6 - 11.04 22:03	8.2	Hr. 22 - 11.05 14:03	5.6	Hr. 38 - 11.06 06:03	4.8
Hr. 7 - 11.04 23:03	6.2	Hr. 23 - 11.05 15:03	4.9	Hr. 39 - 11.06 07:03	2.9
Hr. 8 - 11.05 00:03	7.3	Hr. 24 - 11.05 16:03	6.9	Hr. 40 - 11.06 08:03	5.5
Hr. 9 - 11.05 01:03	5.8	Hr. 25 - 11.05 17:03	6.1	Hr. 41 - 11.06 09:03	5.9
Hr. 10 - 11.05 02:03	5.8	Hr. 26 - 11.05 18:03	5.4	Hr. 42 - 11.06 10:03	6.5
Hr. 11 - 11.05 03:03	4.4	Hr. 27 - 11.05 19:03	2.9	Hr. 43 - 11.06 11:03	5.0
Hr. 12 - 11.05 04:03	5.2	Hr. 28 - 11.05 20:03	3.7	Hr. 44 - 11.06 12:03	5.8
Hr. 13 - 11.05 05:03	4.0	Hr. 29 - 11.05 21:03	5.3	Hr. 45 - 11.06 13:03	5.8
Hr. 14 - 11.05 06:03	6.0	Hr. 30 - 11.05 22:03	3.7	Hr. 46 - 11.06 14:03	6.2
Hr. 15 - 11.05 07:03	3.7	Hr. 31 - 11.05 23:03	6.7	Hr. 47 - 11.06 15:03	3.2
Hr. 16 - 11.05 08:03	5.6	Hr. 32 - 11.06 00:03	5.3	Hr. 48 - 11.06 16:03	5.1

Pressure Chart

